

FSE 2021 OVERALL SCORING RESULTS

Place	Car Num	Team	Business Plan Score	Cost Score	Design Score	Skid Pad Score	Acceleration Score	Autocross Score	Endurance Score	Efficiency Score	Penalty	Total Score
1	E045	UAS Bonn Rhein Sieg	54,7	95,0	150,0	56,2	75,0	58,7	249,3	79,9		818,8
2	E066	CTU in Prague	65,0	81,1	89,0			100,0	325,0	67,0		727,1
3	E032	DHBW Ravensburg	65,4	78,9	128,0			41,8	219,0	84,5		617,5
4	E050	University of Lisbon - Instituto Superior Técnico	66,1	68,9	125,0	61,1	41,7	90,0	57,6	88,4		598,7
5	E097	UAS Schweinfurt	59,4	78,4	16,0		36,4	58,3	160,0	82,4		491,0
6	E051	Universidad de Sevilla	59,0	89,2	89,0	30,0	3,5	12,6	25,0	100,0		408,4
7	E069	University of Ljubljana	52,0	54,4	82,0	71,7	49,9	79,1				389,0
8	E054	ETSEIB (UNIVERSITAT POLITÈCNICA DE CATALUNYA)	66,0	74,4	120,0	75,0	53,1	99,0			-100,0	387,6
9	E048	University of the Basque Country UPV/EHU	56,9	96,3	121,0	55,9	25,3					355,4
10	E046	Chalmers University of Technology	61,6	90,0	125,0							276,6
11	E161	HAWK - HHG		95,3	75,0		12,1	69,5				251,9
12	E146	Politecnico di Torino	52,8	63,3	134,0							250,1
13	E036	TU Chemnitz	73,0	88,2	88,0							249,2
14	E056	University of Navarra	52,4	72,6	92,0							217,0
15	E017	Universidad Pontificia Comillas ICAI - ICADE	69,0	36,7	61,0						-100,0	66,7
16	E028	University of Oviedo	55,8	55,6	49,0						-100,0	60,4

Team with Car Number E017 has received a 100 point penalty due to a violation of FS rule A 3.1.2 and FS Spain Handbook article 8.5: Failure to follow instructions from the officials, after previous warnings and failure to follow the Covid-19 FS Spain health and safety guidelines.

Team with Car Number E028 has received a 100 point penalty due to a violation of FS rule A 3.1.2 and FS Spain Handbook article 8.5: Failure to follow instructions from the officials, after previous warnings and failure to follow the Covid-19 FS Spain health and safety guidelines.

Team with Car Number E054 has received a 100 point penalty due to a violation of FS rule A 3.1.2 and FS Spain Handbook article 8.5: Failure to follow instructions from the officials, after previous warnings and failure to follow the Covid-19 FS Spain health and safety guidelines.